07/11/27 Thursday. 22/11/2007 12:57:21 PM Date User Linda Lacelle **Process Sheet** : REWORK **Drawing Name** : CC-DAR01 Dart Aerospace Ltd. Customer : 35962 Job Number : 10804 **Estimate Number** : D2807041 Part Number P.O. Number : ECN 1019 **Drawing Number** S.O. No. : : 22/11/2007 This Issue Project Number : NC Prsht Rev. : SMALL /MED FAB **Drawing Revision** : 11 Type First Issue Material : 35961 Previous Run Each : 29/11/2007 Qty: Due Date Written By Checked & Approved By Comment **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: PACKAGING RESOURCE #1 PACKAGING 1 1.0 Comment: PACKAGING RESOURCE #1 REMOVE FROM STOCK: D2807 B 333941 SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 2.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 ADD D3671-1 PLACARD B 35613 TO D2807 (BECOMES D2807-041) PER DRWG D2807-041 Gas Spring (Support Prop) 3.0 D2807 50.0000 Each(s) 1.0000 Each(s)/Unit Total: Comment: Qty.: 12 Gas Spring (Support Prop) PLACARD D36711 4.0 50.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: 51 PLACARD INSPECT WORK TO CURRENT STEP 5.0 QC5

Comment: INSPECT WORK TO CURRENT STEP

. mursuay, 22/11/2007 12:57:21 PM Linda Lacelle Customer: CC-DAR01 Dart Aerospace Ltd. **Process Sheet** Drawing Name; REWORK Job Number: 35962 Job Number: Part Number: D2807041 Seq. #: Machine Or Operation: 6.0 PACKAGING 1 Description: PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 RESTOCK USING NEW B/N Job Completion U Still-28 QC 21 - 07.11,28 \$

